

ACCESSIBILITY PLAN

This plan has been created in conjunction with the latest Disability Access Audit to ensure continued improvement of the school site for staff, students and visitors with disabilities.

Building	Area	Description	Comment	Responsibility	Due Date	Completed Date
External	Bushey	Relocate waste bin from the sign board outside the Bushey Building	Bin to be moved to side of sign	SB	April 2015	January 2015
External	Parking	Monitor existing designated parking bays to ensure there is sufficient provision and they are not being misused	Continual monitoring required to ensure spaces are correctly used with email reminders/leaf leting of cars if they are not	SB		On-going
N/A	N/A	Ensure staff have necessary disability awareness training		SLT		
Main	Ground Floor	Provide induction loop signage in reception		ВР	April 2015	February 2015
Main	Ground Floor – Accessible Toilet opposite G10	Do not use as a store		SB	May 2015	
Main	Ground Floor – Accessible Toilet opposite G10	Provide one lock to the door that is easy to use with a clenched fist	Quote in progress with Sodexo	ВР	August 2015	

Main	Ground	Install an	Quote in	ВР	August	
	Floor –	emergency	progress with]	2015	
	Accessible	assistance alarm	Sodexo		2020	
	Toilet					
	opposite					
	G10					
Main	Ground	Install		SB	August	
	Floor –	additional hand			2015	
	Accessible	rails: vertical rail				
	Toilet	to open side of				
	opposite	WC, vertical rail				
	G10	to above the				
		wash hand				
Main	Ground	basin Provide colour		SB	August	
iviaiii	Floor –	contrasting light		36	2015	
	Accessible	pull			2013	
	Toilet	pan				
	opposite					
	G10					
Main	Ground	Ensure		SB	August	
	Floor –	emergency pull			2015	
	Accessible	cord is not tied				
	Toilet	up				
	opposite					
	PD Room					
Main	Ground	Install		SB	August	
	Floor –	additional			2015	
	Accessible Toilet	vertical hand rail above the				
	opposite	wash hand				
	PD Room	basin				
Main	Old	Renew stair		SB	August	
	building	nosing colour			2015	
	staircases	constrasting				
		strips				
Main	First Floor –	Provide colour		SB	August	
	F1	contrasting stair			2015	
		nosing				
Main	First Floor –	Identify a	Room swap	Head of		N/A
	F1	suitable	would occur	Science		
		alternative	when			
		room for when this is	necessary			
		inaccessible to a				
		student/employ				
		ee				
Design	Ground	Provide signage		BP	April 2015	February
- 0	Floor	on inside of			,	2015
	Accessible	door about				
	Toilet	opening into				

		corridor				
Design	Ground Floor Accessible Toilet	Provide pull cord with two bangles at 100mm and 800-1000mm above the floor	Quote in progress with Sodexo	ВР	August 2015	
Design	Ground Floor Accessible Toilet	Provide emergency reset button within reach of the toilet pan	Quote in progress with Sodexo	BP	August 2015	
Design	Ground Floor Accessible Toilet	Provide one lock to the door that is easy to use with a clenched fist	Quote in progress with Sodexo	SB	August 2015	
Design	Ground Floor Accessible Toilet	Remove toilet lid		SB	May 2015	
Design	Ground Floor Accessible Toilet	Provide a horizontal bar to the inside of the door		SB	August 2015	
Sports Hall	Accessible toilet	Ensure emergency pull cord is not tied up in accessible toilet		SB	May 2015	
Sports Hall	Accessible toilet	Ensure maneuvering area in accessible toilet is kept free of obstruction	Area to be cleared and kept clear	Initially SB then whole school	May 2015	
Sports Hall	Accessible toilet	Install additional vertical hand rail above the wash hand basin		SB	August 2015	
Sports Hall	Accessible toilet	Provide one lock to the door that is easy to use with a clenched fist	Quote in progress with Sodexo	SB	August 2015	
Sixth Form		Provide colour contrasting nosings to		ВР	August 2015	

		entrance steps				
Sixth	Reception	Make exit	Only affects	BP	August	
Form		button readily	out of hours		2015	
		identifiable	usage			
Sixth	Staff toilets	Ensure		SB	May 2015	
Form		emergency pull				
		cords are not				
		tied up				
Sixth	Staff toilets	Provide second		SB	August	
Form		vertical support			2015	
		rails above the				
		wash hand				
		basins				
Sixth	Staff toilets	Provide one lock		SB	August	
Form		to the door that			2015	
		is easy to use				
		with a clenched				
		fist				
Sixth	Female	Replace broken		SB	August	
Form	Staff Toilet	seat			2015	
Sixth	Male Staff	Remove gap		SB	August	
Form	Toilet	front seat and			2015	
		replace with a				
		complete seat				
Sixth	Student	Provide second		SB	August	
Form	Accessible	vertical support			2015	
	Toilets	rails above the				
		wash hand				
61 .1	0. 1 .	basins				
Sixth	Student	Provide one lock		SB	August	
Form	Accessible	to the door that			2015	
	Toilets	is easy to use				
		with a clenched				
		fist				

Staff responsible	Facilities & IT Leader	Monitoring & Evaluation by	Full Governors
Governors Committee Responsible	Health, Safety and Premises		
Date approved by Governors	June 2015	Review Date	May 2018